

Figure 3. *Sensitivity reduction at low frequency unavoidably leads to sensitivity increase at higher frequencies.*

from "Respect the Unstable" by Gunter Stein, IEEE Control Systems Magazine, August 2003




Figure 4. *Sensitivity shaping automated by modern control tools.*

from “*Respect the Unstable*” by Gunter Stein, IEEE Control Systems Magazine, August 2003